

Service Information

Mazda Motor Corporation

3-1, Shinchi, Fuchu-cho, Aki-gun
Hiroshima 730-8670, Japan
TEL : 81(82)287-5323
FAX : 81(82)287-5220



Category T	Technical	Ref. No. E015/15	Page 1 of 1
Coverage <input type="checkbox"/> Distributor only <input checked="" type="checkbox"/> Please inform your dealers		Date Issued September 10, 2015	
Please convey this information to your <input type="checkbox"/> Director <input checked="" type="checkbox"/> General Manager <input checked="" type="checkbox"/> Warranty Dept. <input checked="" type="checkbox"/> Parts Dept. <input checked="" type="checkbox"/> Training Dept. <input checked="" type="checkbox"/> Field Rep.		Date Revised	
Applicable Model Mazda2 (DJ), Mazda3 (BM), Mazda6 (GJ), CX-3(DK), CX-5 (KE) and MX-5 (ND)		Applicable Countries or Specifications Europe (LHD and RHD markets)	

Subject: Adjustment of Headlights Optical Axis is not necessary when driving LHD vehicle in RHD country or vice versa

DESCRIPTION

When you receive a customer inquiry about the above subject matter, please explain to the customer as below.

Copy from Owner's Manual (The description has been added to the latest versions.)

Headlights are equipped which do not blind drivers approaching in the opposite direction no matter what side of the road you must drive your vehicle (left-hand or right-hand traffic). Therefore, it is not necessary to adjust the optical axis of the headlights when switching temporarily to driving on the opposite side of the road (left-hand or right-hand traffic).

NOTE: In case the customer registers the vehicle for permanent use in a country of the opposite side driving for moving etc., it is recommended to check and follow any local regulation.

Ryu Shimizugawa
Manager, Technical Information Gr.
Technical Service Dept.
Mazda Motor Corporation